

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:	Examiner: J. Rahll Group Art Unit: 2874
MAMORU UCHIDA	
Appl. No.: 10/532,720	
Int'l Filing Date: December 5, 2003	
§ 371(c) Date: April 27, 2005	Certificate
For: PHOTONIC CIRCUIT BOARD)
U.S. Patent No.: 7,386,200 B2	Certificate OCT 0 2 2008 of Correction
Issued: June 10, 2008) September 26, 2008

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

OCT 2 2008

10/01/2008 SZEWDIE1 00000053 7386200 01 FC:1811 100.00 OP Patentee's undersigned attorney may be reached in our Costa Mesa,


California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

Edward A. Kmett Attorney for Patentee Registration No.: 42,746

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

FCHS_WS 2509693v1



OCT 2 2008

Staple PRINTER'S TRIM LIN Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 7,386,200 B2

DATED

: June 10, 2008

INVENTOR(S) : Uchida

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER SHEET:

(56) "EP 1 219 994 A2 7/2002" should be deleted;

(56) "JP 6 69490 11/1994" should be deleted;

(56) "JP 7 183629 7/1995" should be deleted;

(56) "JP 9 214073 8/1997" should be deleted;

(56) "JP 10 341063 12/1998" should be deleted;

(56) "10/341063" should read -- 10-341063 --; and

(56) "WO 01/33895 A2 5/2001" should be deleted.

COLUMN 5:

Line 38, "(PLDS)" should read -- (PLDs) --.

COLUMN 6:

Line 46, "can" should read -- can be --.

COLUMN 7:

Line 6, "delayor" should read -- delay or --.

COLUMN 11:

Line 54, "PLDS)" should read -- PLDs) --.

2 2008 OCT

MAILING ADDRESS OF SENDER:

PATENT NO. <u>7,386,200 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) FCHS_WS2510229v1 No. of add'l. copies @ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

: 7,386,200 B2

DATED

: June 10, 2008

INVENTOR(S) : Uchida

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER SHEET:

(56) "EP 1 219 994 A2 7/2002" should be deleted;

(56) "JP 6 69490 11/1994" should be deleted;

(56) "JP 7 183629 7/1995" should be deleted;

(56) "JP 9 214073 8/1997" should be deleted;

(56) "JP 10 341063 12/1998" should be deleted;

(56) "10/341063" should read -- 10-341063 --; and

(56) "WO 01/33895 A2 5/2001" should be deleted.

COLUMN 5:

Line 38, "(PLDS)" should read -- (PLDs) --.

COLUMN 6:

Line 46, "can" should read -- can be --.

COLUMN 7:

Line 6, "delayor" should read -- delay or --.

COLUMN 11:

Line 54, "PLDS)" should read -- PLDs) --.

0CT**2** 2008

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

FCHS_WS2510229v1

PATENT NO. 7,386,200 B2

No. of add'l. copies @ 30¢ per page